

DATE: September 24, 1970

TO: Owners and Operators of Yankee Aircraft

SUBJECT: Vendor Service Publications

MODELS AFFECTED: All Model AA-1

TIME OF COMPLIANCE: As called out on vendor publications.

Attached for your service information files are copies of vendor service publications covering accessory items listed below. It is recommended that compliance with these publications be made as called out in the individual service bulletin/letter.

ITEM 1 - Slick Magneto Replacement

Lycoming Service Letter No. L173 recommends that Slick magnetos be exchanged at 900 hours of magneto log time.

ITEM 2 - Carburetor Throttle Arm Screw

Lycoming Service Bulletin No. 330 recommends the throttle arm lock screw be retorqued and safe-tied within the next 100 hours.


NOTE: Item 3 & 5 of American Aviation Corporation Service Letter No. 69-4 cover this same subject.

ITEM 3 - Alternator Oil Seal

Prestolite Aircraft Service Bulletin No. ASM-2 covers corrective action for loose slip ring end oil seals in Prestolite Part No. ALE-6406, Lycoming Part No. 78401 Alternators.

Very truly yours,

AMERICAN AVIATION CORPORATION


Paul H. Seibert
Customer Service Manager

PHS:pjr

Distribution (A)